การวัดและวิเคราะห์การสั่นสะเทือนของการขนส่งในประเทศไทยและการประยุกต์ในการจำลอง สภาวะการขนส่งผลไม้เขตร้อน

เคชพันธุ์ สวัสดี*

บทคัดย่อ

การวัดค่าการสั่นสะเทือนของการขนส่งด้วยรถบรรทุกและรถไฟบนเส้นทางสายหลักทั้งสิ่ภูมิภาคของประเทศ พบว่าค่าการสั่นสะเทือนในแนวตั้งสูงกว่าแนวซ้ายขวาและแนวหน้าหลังตามลำดับ โดยผลการวิเคราะห์การ สั่นสะเทือนแสดงในรูปค่าเฉลี่ย Grms ของการขนส่งค้วยรถบรรทุกมีค่าสูงที่สุดในภาคเหนือ (0.353) ภาคใต้ (0.246) ภาค ตะวันออกเฉียงเหนือ (0.197) และภาคตะวันออก (0.139) ตามลำดับ ขณะที่การสั่นสะเทือนของการขนส่งทางรถไฟมีค่า สงที่สดในภาคตะวันออก (0.097) ภาคใต้ (0.095) ภาคเหนือ (0.064) และภาคตะวันออกเฉียงเหนือ (0.059) ตามลำคับ การเปรียบเทียบการตอบสนองต่อแรงกระทำเชิงกลของผลไม้เขตร้อนในสภาวะจำลองการขนส่งโดยวิธีการทดสอบ ASTM D 999 โดยใช้ตะกร้าหูเหล็ก (RPC-TH) พบว่ามะละกอแขกคำมีเปอร์เซ็นต์ผลเสียหายมากที่สุด (44.95%) เมื่อ เปรียบเทียบกับฝรั่งแป้นสีทอง (36.95%) มังคุด (21.50%) มะละกอโซโล (19.09%) และส้มสายน้ำผึ้ง (13.33%) ตามลำดับ จากผลการทดลองนำมาแบ่งกลุ่มผลไม้เขตร้อนตามการตอบสนองต่อแรงกระทำเชิงกล 3 กลุ่ม ได้แก่ การ ตอบสนองต่อแรงกระทำเชิงกลต่ำ (< 20%) ปานกลาง (21-40%) และสูง (> 40%) ทำการเปรียบเทียบความสามารถใน การป้องกันของบรรจุภัณฑ์เพื่อการขนส่งต่างๆ โดยใช้มังคุดเป็นผลไม้ต้นแบบ ทำการทดสอบการสั่นสะเทือนตามวิธีการ ทคสอบ ASTM D 999 พบว่ามังคุดที่บรรจุในตะกร้าพลาสติกหูเหล็กที่นิยมใช้ในการขนส่งผลไม้ในประเทศไทย (RPC-TH) ขนาคภายใน 52 x 32.5 x 30 ซม. มีความเสียหายมากที่สุด เมื่อเปรียบเทียบกับตะกร้าพลาสติกที่ใช้ในการขนส่ง ผลใม้ในประเทศสหรัฐอเมริกาแบบ A (RPC-US-A) ขนาดภายใน 58 x 37 x 27 ซม. และแบบ B (RPC-US-B) ขนาด ภายใน 37 x 27.5 x 16.5 ซม. ทำการเปรียบเทียบสภาวะจำลองการขนส่งตามวิธีการทดสอบต่าง ๆ โดยใช้มังคุดเป็น ผล ใม้ต้นแบบพบว่าการทดสอบตามวิธีการของ ISTA 1A มีเปอร์เซ็นต์ความเสียหายของมังคดสงที่สด (33.50%) เมื่อ เปรียบเทียบกับวิธีการทศสอบ ISTA 4AB (22.75%) ASTM D 999 (21.50%) ASTM D 4728 (19.00%) และสภาวะการ ขนส่งจริง (16.75%) พบว่าเปอร์เซ็นต์ความเสียหายของมังคุคโดยวิธีการทดสอบ ASTM D 4728 ซึ่งใช้ข้อมูลการ สั่นสะเทือนทางรถบรรทุกของประเทศไทยมีค่าใกล้เคียงกับสภาวะการขนส่งจริงมากที่สุด

^{*} วิทยาศาสตรมหาบัณฑิต (เทคโนโลยีการบรรจุ) คณะอุตสาหกรรมเกษตร มหาวิทยาลัยเกษตรศาสตร์. 153 หน้า.

Measurement and Analysis of Vibration Distribution in Thailand and the Applications in the Simulated Tests for Tropical Fruits

Dathpan Sawatdee

Abstract

The vibration levels in truck and rail shipments of the major routes in Thailand (North, South, East, and Northeast in Thailand) were measured and analyzed. The results showed that vertical vibration levels were higher than lateral and longitudinal vibration levels, respectively. The average Grms for truck vibration were highest in the Northern route (0.353), followed by the Southern route (0.246), Eastern route (0.197), and the North-Eastern route (0.139), respectively. The average Grms for rail vibration were highest in the Eastern route (0.097), followed by the Southern (0.095), Eastern (0.064), and the North-Eastern (0.059), respectively. Selected tropical fruits were tested for their susceptibility to mechanical damage, according to ASTM D 999 using the reusable plastic containers generally being used for produce distribution in Thailand (RPC-TH). The results showed that Khagdum papaya had the highest percentages of damage (44.95%) as compared to guava (36.95%), mangosteen (21.50%), Solo papaya (19.09%), and tangarine (13.33%), respectively. Percentages of damage from the vibration test were used to classify the susceptibility of fruits to mechanical damage as low (< 20%), moderate (21-40%), and high (> 41%). Simulated vibration tests were performed to evaluate the shipping containers based on their protective performances. Three different distribution packages used in this study were the reusable plastic containers currently being used for produce distribution in Thailand (RPC-TH) and USA (RPC-US-A, RPC-US-B) with inside dimensions 52 x 32.5 x 30 cm, 58 x 37 x 27 cm, and 37 x 27.5 x 16.5 cm, respectively. The results with mangosteens showed the highest percentages of damage in RPC-TH as compared to RPC-US-A and RPC-US-B by ASTM D 999 simulated test. Different test methods were performed for mangosteen distribution. ISTA 1A resulted in the highest percentages of mangosteen damage (33.50%), followed by ISTA 4AB (22.75%), ASTM D 999 (21.50%), ASTM D 4728 (19.00%), and the real shipment (16.75%). The results indicated that percentages damage of mangosteen simulated by ASTM D 4728 using Thailand truck vibration data were closest to those by the real shipments.

_

^{*} Master of Science (Packaging Technology), Faculty of Agro-Industry, Kasetsart University. 153 pages.